



111707370_1_9cf8a4d-449d-47d5-83a7-bd31517a8de6

2. Color matching / Preparation / Paint Booth Use Time

Type of Topcoat	Number of Layers	Number of outer panels					Extra specification Poor Hiding color
		1 panel	2 panels	3 panels	4 panels	5 panels or more	
Solid	1-coat	2.2	2.2	2.2	2.2	2.2	+0.3
	2-coat	2.3	2.3	2.3	2.3	2.3	
Metallic		2.7	2.8	2.9	3.1	3.2	
2-coat Pearl		2.7	2.8	2.9	3.1	3.2	
3-coat Pearl	3-coat	3.7	4.0	4.3	4.5	4.8	

The number of panels refer to the number of outer panel which the color base coat is applied to.

Note : Painting only the bumper cover, don't use this table.

111707370_1_9c23b301-ce23-4a0e-b507-417de1fd8d24

3. Bumper Cover Painting Time

Item			Replacement	Deformation Repair	Scratch Repair		Color matching
	Type of Topcoat	number of Layers			Large (21-35cm)	Small (10-20cm)	
Front	Solid	1-coat	2.1	3.9	3.2	3.0	+0.4
		2-coat	2.2	4.0	3.3	3.1	+0.4
	Metallic		2.3	4.1	3.4	3.2	+0.5
	2-coat Pearl		2.3	4.1	3.4	3.2	+0.5
	3-coat Pearl	3-coat	2.5	4.4	3.7	3.4	+0.7
Rear	Solid	1-coat	2.1	3.9	3.2	3.0	+0.4
		2-coat	2.2	4.0	3.3	3.1	+0.4
	Metallic		2.3	4.1	3.4	3.2	+0.5
	2-coat Pearl		2.3	4.1	3.4	3.2	+0.5
	3-coat Pearl	3-coat	2.5	4.4	3.7	3.4	+0.7

Deformation repair includes putty repair for a damaged length of approx. 21cm.

Scratch repair includes putty repair. **Large** : 21-35cm in length **Small** : 10-20cm in length

Color matching : When painting only bumper cover, add color matching time only once.

111707370_1_a197193f-8dc8-41ca-a480-c1e381728972

1. External Panel Painting Time

1) Application Time

No.	Panel Name	area (dm ²)	Repair method															
			Replacement						Repair									
			New part		Extra specification		Extra work Rustproof Wax	1/1 paint		1/2 paint		1/3 paint		Extra specification		Extra work		
Multiple	Single	Poor hiding color	2-coat Solid	0.1 / 1part	Multiple	Single	Multiple	Single	Multiple	Single	Poor Hiding color	2-coat Solid	0.1 / 1part	0.1 / 1part				
1	Hood Sub Assy	174	2.6	3.4	+0.4	+0.1	+0.1	4.4	4.8	3.2	3.6	2.6	3.0	+0.3	+0.1	+0.1	+0.1	
2	Fender Sub Assy Front	43	1.5	2.0	+0.4	+0.1	—	2.3	2.7	1.7	2.1	1.6	2.0	+0.3	+0.1	—	—	
3	Front Door Panel Sub Assy	91	2.2	2.9	+0.4	+0.1	+0.1	3.3	3.7	2.3	2.7	2.0	2.4	+0.3	+0.1	+0.1	+0.1	
4	Rear Door Panel Sub Assy	88	2.1	2.8	+0.4	+0.1	+0.1	3.3	3.7	2.3	2.7	1.9	2.3	+0.3	+0.1	+0.1	+0.1	
5	Quarter Panel *1	104	3.1	3.8	+0.4	+0.1	—	3.5	3.9	2.5	2.9	2.0	2.4	+0.3	+0.1	+0.1	—	
6	Back Door Panel Sub-Assy	123	2.6	3.5	+0.4	+0.1	+0.1	3.8	4.2	2.7	3.1	2.2	2.6	+0.3	+0.1	+0.1	+0.1	
7	Body Lower Back Panel Sub Assy	20	1.5	1.9	+0.4	+0.1	—	1.7	2.1	1.4	1.8	1.4	1.8	+0.3	+0.1	+0.1	—	
8	Roof Panel *2	304	4.9	6.4	+0.7	+0.3	—	5.8	6.2	4.4	4.8	3.6	4.0	+0.6	+0.3	+0.1	—	
9	Rocker Panel Outer	25	1.6	1.8	+0.4	+0.1	—	1.5	1.9	1.5	1.9	1.5	1.9	+0.3	+0.1	—	—	

Replacement Panel : includes surface preparation and applying body sealant.

Repair Panel : includes surface preparation.

*1:(incl.) Back Door Opening Side Frame Sub-Assy

*1:(incl.) Roof Side Rail Outer

1/1, 1/2, 1/3 are the proportions of the panel surface that the base coat is applied to.

Note: For **spot panels**, the replacement includes refinishing of the related areas.

2) Blending Time

③ Blending time

Type of Topcoat	Time
Metallic 2-coat paint	1.0
3-coat paint	1.1

This work time can be added only once, when blending is required during repair.

111707370_1_b1fcdfe4-005a-420a-aa63-4047c428dc7f



111707370_1_fb56265c-c588-404f-8782-181940af8519



111707370_1_8aa00289-f61a-4d30-9898-21469e0a40db



111707370_1_b43e6a38-7514-4320-bdd0-6ddc9e8262fd



111707370_1_9d405269-9094-46f6-abc0-2a1c7886acc2



111707370_1_8bae2804-c15e-4eab-8a5e-8f4b0b8607af



111707370_1_3cd1f4db-c29c-4495-a639-f37a587f2f48



111707370_1_2e1af956-49ff-4fe2-a230-192a2a9f1996