



**ASTURIAS SOLUCIONES DE INGENIERIA, BUCEO
COMERCIAL Y DRAGADO SAS**
Nit. 900.382.411-7

UNDERWATER INSPECTION REPORT

• **PORT** : **BUENAVENTURA - COLOMBIA**
• **DATE** : **26 JUNE 2024**
• **VESSEL** : **ZIM LUANDA**
• **NACIONALITY** : **VALLETTA**
• **IMO** : **9403229**

At present day, we proceed to make an underwater inspection at motor vessel "ZIM LUANDA" Concerning to hull visual inspection report.

For the operation was supported by a dive supervisor, two divers, a surface assistant, and a boat with his driver.

Inspection begins in the forward direction port side to aft and continues to starboard at forward. After the inspection, the following is concluded:

1. The vertical sides and Bottom hull are in good condition, without damages. There are no signs of blows, dents, or bends without scuffmarks or indentations.
2. The ruder is in good conditions, without damages.
3. Welds are in good condition without pores.
4. The main propeller has six 06 blades; these are in good conditions without damages. Please note, it was found a rope fishing net entangle inside the rope guard and the shaft.
5. The rope guard is in good condition free of damages and the oil seals are closed and secured with steel wire, without leaks.
6. The bilge keels on both sides are in good conditions. Weld beads are in good condition. do not have folds, fissures, or dents.
7. The Seachests on both sides are free of damages; these are secured all with bolts and nuts.
8. **No contraband or strange elements were found on it at the time of the visual underwater inspection.**

This inspection was made at **Berth TCBUEN** - Buenaventura, Colombia and began at 07:35 hours and ended at 08:20 hours, with 2 scuba divers.

Sincerely yours.

SEBASTIAN GIRALDO
Diving Supervisor

CAPTAIN
MV ZIM LUANDA



Dirección: Cl 1 # 7ª-85 Br. Pueblo Nuevo
Teléfono: 2412401 – Celular: +57 314 5030445
Email: bunops@asturiasingenieria.com /
gerencia@asturiasingenieria.com
Buenaventura, Colombia